

A FLECK PERFORMANCE BULLETIN

Bulletin No. 341

☐ Product ☐ Application ☒ Service

news from Fleck Controls

May 28, 1999

2900 Lower Drive Cam Improvement

This new cam is stronger and has a molded hole for the connecting rod bearing. Having the molded hole, always in a fixed position, allows for a consistent alignment of the micro switches on the cam and increase product reliability. This change was implemented on May 1, 1999.

Part numbers: 28164 (ex 24214) 2900 Adaptor drive cam assembly


SIDE VIEW



Old Style

New Style

TOP VIEW



If you have any questions or comments, please do not hesitate to contact us.
Thank you,

Jay Rumble